

110V~ 50/60Hz 4h	230V~ 50/60Hz 3p=6h 4p+5p=9h	400V~ 50/60Hz 3p=9h 4p+5p=6h	500V~ 50/60Hz 7h	>50- 500V~ 100-300Hz 10h	>50- 500V~ 301-500Hz 2h
Cat.No.	Cat.No.	Cat.No.	Cat.No.	Cat.No.	Cat.No.

Amp.	Poles	pack. unit	110V~ 50/60Hz 4h	230V~ 50/60Hz 3p=6h 4p+5p=9h	400V~ 50/60Hz 3p=9h 4p+5p=6h	500V~ 50/60Hz 7h	>50- 500V~ 100-300Hz 10h	>50- 500V~ 301-500Hz 2h
16	3	10	113-4	<b>113-6</b>	113-9	113-7	113-10	113-2
16	4	10	114-4	114-9	<b>114-6</b>	114-7	114-10	114-2
16	5	10	115-4	115-9	<b>115-6</b>	115-7	115-10	115-2
32	3	10	123-4	<b>123-6</b>	123-9	123-7	123-10	123-2
32	4	10	124-4	124-9	<b>124-6</b>	124-7	124-10	124-2
32	5	10	125-4	125-9	<b>125-6</b>	125-7	125-10	125-2



113-6

16	3	10	113-4TT	<b>113-6TT</b>	113-9TT			
16	4	10	114-4TT	114-9TT	<b>114-6TT</b>			
16	5	10	115-4TT	115-9TT	<b>115-6TT</b>			
32	3	10	123-4TT	<b>123-6TT</b>	123-9TT			
32	4	10	124-4TT	124-9TT	<b>124-6TT</b>			
32	5	10	125-4TT	125-9TT	<b>125-6TT</b>			



113-6TT

16	3	5	913-4	<b>913-6</b>	913-9	913-7	913-10	913-2
16	4	5	914-4	914-9	<b>914-6</b>	914-7	914-10	914-2
16	5	5	915-4	915-9	<b>915-6</b>	915-7	915-10	915-2
32	3	5	923-4	<b>923-6</b>	923-9	923-7	923-10	923-2
32	4	5	924-4	924-9	<b>924-6</b>	924-7	924-10	924-2
32	5	5	925-4	925-9	<b>925-6</b>	925-7	925-10	925-2



915-6

16	3	5	913-4w	<b>913-6w</b>	913-9w	913-7w	913-10w	913-2w
16	4	5	914-4w	914-9w	<b>914-6w</b>	914-7w	914-10w	914-2w
16	5	5	915-4w	915-9w	<b>915-6w</b>	915-7w	915-10w	915-2w
32	3	5	923-4w	<b>923-6w</b>	923-9w	923-7w	923-10w	923-2w
32	4	5	924-4w	924-9w	<b>924-6w</b>	924-7w	924-10w	924-2w
32	5	5	925-4w	925-9w	<b>925-6w</b>	925-7w	925-10w	925-2w



913-6w

- 
- 
- 
- 
- 
- 
- 
- 
- 
-